



VW Golf III build year from 1991 to 1999 Headlamp-retrofit

Retrofit from the standard to the GT/GTI/VR6 version.

When carrying out a headlamp-retrofit on the request of a customer ensure during installation, that the bridge contact is fitted to connector 10 in the fuse box.

If the vehicle is equipped with factory fitted fog lamps, remove plug or relay, fit the contact bridge (bridge pins 3 and 4) and refit plug or relay. (Fig I)

This contact bridge is absolutely necessary, otherwise when The main beam is switched on, the dip lights go out.

Due to the dip- and main beam being produced by two different reflectors, the non operation of the dip light would create a very dark area on the road in front of the vehicle, this of course being dangerous.




Fig I

Bulletin