

# PEUGEOT 407 - Pollen filter clogged | HELLA

**PEUGEOT**

**407**

**Model year: from 2004**

**Right-hand drive (RHD)**

If, on the above mentioned vehicles there are complaints about a degradation in the function of the heater blower motor or air-conditioning blower motor and a reduced air flow is also apparent in the vehicle interior, the pollen filter is a possible cause of the problem.

Even though the vehicles may have only covered less than 10000 km since the last replacement of the pollen filter, in this case the pollen filter could be clogged again.

As a rectification measure fit the modified pollen filter.

1 unit. - Pollen filter: (service part no.) ET no. 6479 04.

- The figures show the "right-hand drive" design in the area of the passenger's footwell.